
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/21/2009
Test to be performed:  Smoke Dyed Water X		Supervisor: JAW
Manhole_ID: S04O018MH	Test ID: <u>D1032-002065</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S04O018MH
0			Water Level	
2			Dye Test Visible	IR@ drop connection jt, 5 GPM
2			General Observation	DROP CONNECTION , DYE LEAKING IN
2			Abandoned Survey	NO MORE DYE SEEN